

Стоимость ремонта снятых с автомобиля электронных блоков безопасности (SRS) автомобиля марки Infiniti: 3500 - 4500 рублей.

Модель	Номер блока	Стоимость ремонта
EX35	988201BA0A Autoliv 609 58 66 00	3500
EX35	988201BA0B Autoliv 609 58 66 00	3500
EX35	988201BF0A	3500
EX35	988201BM0A	3500
FX35	988201CA0A Autoliv 609 58 67 00	3500
FX35	988208Y70A	3500
FX35	988208Y72B	3500
FX35	98820CG000	3000
FX35	98820CG100	3500
FX35	98820CG10A	3500
FX35	98820CG700	3500
FX35	98820CL70A	3500
FX35	98820CL71A	3500
FX35	98820CL72B	3500
FX37	988201WW0A	3500
FX45	988201CM0A	3500
FX45	98820CG000	3500
FX45	98820CG700	3500
FX50	988201WW0A	3500
G20	988207J100	3500
G35	988201BA0A Autoliv 609 58 66 00	3500
G35	988201BA0B Autoliv 609 58 66 00	3500
G35	988201NC0A	3500
G35	98820AC700	3500
G35	98820AC70A	3000
G35	98820AC800	3000
G35	98820AC80A	3000
G35	98820AC900	3500
G35	98820AM000	3000
G35	98820AM600	3000
G35	98820AM700	3000
G35	98820CF90A	3500
G35	98820CM30A	3500
G35	98820CM40A	3000
G35	98820JK600	3000
G35	98820JK800	3500
G37	988201NCOA	3500
G37	988201ND0A	3500
G37	98820JL00A	3500
G37	98820JL03B	3500

G37	98820JL20A	3500
I30	988201L226	3500
I30	988201L270	3500
I30	988204L700	3500
I30	988204L705	3500
I30	988204Y725	3500
I35	988205Y805	3000
M35	98820EH100	3500
M35	98820EH30A	3500
M35	98820EJ20A	3000
M35	98820EV50A	3500
M37	98820 1ME0A Bosch F01G07205P	3500
M45	98820CR900	3500
QX4	988202W105	3500
QX4	988204W600	3500
QX4	988205W915	3500
QX56	28556EB50B	3500
QX56	988207S705	3500
QX56	988207S706	4000
QX56	98820ZC51A	4000
QX56	98820ZE10C	4000
QX56	98820ZQ41A	4000