

Стоимость ремонта снятых с автомобиля электронных блоков безопасности (SRS) автомобиля марки Mitsubishi: 2500 - 4000 рублей.

Модель	Номер блока	Стоимость ремонта
ASX	8635A215 Bosch F01G07203L 4000	
Carisma	0 285 001 290 Bosch 3500	
Carisma	MR158433 Bosch 0 285 001 1273000	
Carisma	MR309115 DB Bosch 0 285 001 233000	
Carisma	MR309212 Bosch 0 285 001 2323000	
Carisma	MR913789 DPB Bosch 0 285 001 286	3000
Colt	0 285 001 646 Bosch	3500
Colt	8635A210 DPSB Bosch 0 285 001 645	3500
Colt	8635A222 DPB Bosch 0 285 010 690	3500
Colt	98078700010DPSB Bosch 0 285 001 936	3500
Colt	MR587271 DPB	3500
Colt	MR587416 DPB Bosch 0 285 001 684	3500
Colt	MR587416 DPSB Bosch 0 285 001 686	3000
Colt	MR587417 DPSB Bosch 0 285 001 685	3500
Colt	MR587757 DPSB Bosch 0 285 001 686	3000
Colt	MR587759 DPSCB Bosch 0 285 001 689	3500
Eclipse	MN141170 DPSBC W2T64071	3000
Eclipse	MR359161	3000
Eclipse	MR530103 DP X6T43774	3000
Eclipse	MR530105 DPS X6T43674	3000
Galant	635A040 DPSB W2T63571	3000
Galant	8635A044 DPSBC W2T64671	3000
Galant	8635A127 DPB W2T65071	3000
Galant	MR309232 DPS X6T4208	2500
Galant	MR522397	3000
Galant	MR522968 DP X6T43771	3000
Grandis	8635A155 DPSBC W2T65373	3500
Grandis	MN141401 W2T62674	3000
Grandis	MR587491 W2T62271	3500
L200	8635A149 DPB W2T65473	4000
L200	MR400743D	4000
L200	MR522940 DP X6T41784	4000
L200	MR522940DP X6T41784	4000
L200	MR530002 DP v1 Denso	3500
L200	MR530002 DP v2 Denso	3500
L200	MR587974 DPB W2T64371	4000
Lancer	8635A079 DB W2T62177	3000
Lancer	8635A221 Bosch F01G07203M	3000
Lancer	MB953173B X6T39783	3000
Lancer	MN141 038	2500

Lancer	MN141 039 DPB W2T62171	3000
Lancer	MN141 249 DPB W2T62474	3000
Lancer	MN141 261 DPSBC W2T62175	3000
Lancer	MN141 262 W2T62174	2500
Lancer	MN141 471	2500
Lancer	MN141 473 W2T62176	2500
Lancer	MR359828 DPS X6T42471	3000
Lancer	MR537995	3000
Lancer	MR587 169 DPB X6T43376A	3000
Lancer	MR587169 DPB X6T43376A	3000
Lancer	P8635A059	3000
Lancer	P8635A060	2500
Lancer	P8635A062	3000
Lancer	P8635A064	3000
Lancer	P8635A073	3000
Lancer	P8635A122	3000
Lancer	P8635A131	3000
Lancer	P8635A133	3000
Lancer	P8635A145	3000
Lancer	P8635A146	3000
Lancer	P8635A168	3000
Lancer	P8635A244	3000
Lancer	P8635A254	3000
Lancer	P8645A133	3000
Lancer	W2T63871	2500
Mirage	MR490 882	3000
Montero	MR268168 DP X6T41181	3000
Montero	MR472776 Denso 152300-3460	3000
Montero	MR482500	3000
Montero	MR482599 DP	3000
Outlander	8635A215 Bosch F01G07203L	3500
Outlander	8635A221 Bosch F01G07203M	3500
Outlander	MN141448 DPB W2T63371	3500
Outlander	MN141500	3500
Outlander	MR587731	3000
Outlander	MR587867 DPB W2T61971	3500
Outlander	MR587868 W2T61972	3000
Outlander	P8635A029	3500
Outlander	P8635A053	3500
Outlander	P8635A116	3500
Outlander	P8635A121	3500
Outlander	P8635A128	3500
Outlander	P8635A144 DDPSC B1	3500
Outlander	P8635A205	3500
Outlander	W2T63372	3500
Pajero	8635A090L DPSCB W2T64873	4000

Pajero	8635A091 DPB W2T64891	4000
Pajero	8635A092S DPSBC W2T54892	4000
Pajero	8635A093L DPSBC	4000
Pajero	8635A183L DPSBC W2T66873	4000
Pajero	MR213889	4000
Pajero	MR268156 Denso 152300-2461	3500
Pajero	MR268157 Denso 152300-1052	3500
Pajero	MR268157 Denso 152300-2471	3500
Pajero	MR268168 DP X6T41181	4000
Pajero	MR472773 DP Denso 152300-3430	4000
Pajero	MR472774 Denso 152300-3440	4000
Pajero	MR472776 Denso 152300-3460	3500
Pajero	MR530002 DP X6T41781	3500
Pajero	MR551784	3500
Pajero	MR587868	4000
Pinin	MN141579DPB W2T63171	3000
RVR	8635A221 Bosch F01G07203M	3000
Space Wagon	MR318479 DPSB Bosch 0 285 001 244	3500
Space Wagon	MR912128 DPSB Bosch 0 285 001 379	3500
Space Wagon	0 285 001 787 Bosch	3000
Space Wagon	MR587814 DPB Bosch 0 285 001 375	3500
Strada	MR530002 DP v1	3000
Strada	MR530002 DP v2	3000