

Стоимость ремонта снятых с автомобиля электронных блоков безопасности (SRS) автомобиля марки Daewoo: 2500 - 3500 рублей

Модель	Номер блока	Стоимость ремонта
Espero	96 187 127 Siemens 5WK4117	3500
Kalos	96 406 171 Siemens 5WY64019	3000
Kalos	96 411 996	3000
Kalos	96 430 713	3000
Kalos	96 534 479	3500
Kalos	96 534 481	3000
Lacetti	96 406 714	3500
Lacetti	96 435 584 Siemens 5WY67019	3500
Lacetti	96 442 702	3500
Lacetti	96 556 998 Siemens 5WY66008	3500
Lanos	96 217 003 Siemens 5WK4155	3000
Lanos	96 220 439	3000
Lanos	96 314 931	3000
Lanos	96 387 636	3500
Lanos	96 387 637 Siemens 5WK43064	3000
Lanos	96 439 951	2500
Lanos	96 534 479	3500
Lanos	96 603 737	3500
Lanos	96 802 931	2500
Lanos	96 818 875	2500
Leganza	96 225 913	3000
Magnus	96 406 536 Siemens 5WY64040	3000
Matiz	94 565 073	3000
Matiz	96 314 931	3500
Matiz	96 314 932 Siemens 5WK4202	3000
Matiz	96 336 886	3000
Matiz	96 484 978	3500
Matiz	96 603 736	3500
Matiz	96 603 737	3000
Matiz	96 603 738	3500
Matiz	96 603 739	3500
Matiz	96 861 792 Siemens 5WY64091	3000
Nubira	96 030 364	3000
Nubira	96 312 353	3500
Nubira	96 312 354	3500
Nubira	96 406 716	3000
Nubira	96 818 874 Siemens	3000
Tacuma	96417796	3500
Tosca	95 947 051 Continental 5WY67126	3000
Tosca	96 945 702 5WY67014	3000

Winstorm	96810867	3000
Winstorm	96866797	3000