

Стоимость ремонта снятых с автомобиля электронных блоков безопасности (SRS) автомобиля марки Hyundai: 2500-3500 рублей

Модель	Номер блока	Стоимость ремонта
Accent	95910-1E000 Mobis 1E959-10000	3000
Accent	95910-1E100 Mobis	3000
Accent	95910-1E150 Mobis	3000
Accent	95910-1E250 Mobis	3000
Accent	95910-1E900 Mobis 1E959-10900	3000
Accent	95910-25200	2500
Accent	95910-25200 Siemens 5WK42928	3000
Accent	95910-25300 Siemens 5WK42929	3000
Accent	95910-25500 Siemens 5WK42931	2500
Accent	95910-25600 Siemens 5WK42932	2500
Accent	95910-25700 Siemens 5WK42933	3000
Accent	95910-25800 Siemens 5WK43070	2500
Atos	95910-02000	3000
Atos	95910-02001	3000
Atos	95910-02101	3000
Atos	95910-02200	3000
Avante	95910-2H000 Mobis	3000
Avante	95910-2H100 Mobis	3000
Avante	95910-2H200 Mobis	3000
Azera	95910-3L000 Bosch 0 285 001 818	3000
Azera	95910-3L010 Delphi SA3109700-00 Bosch 0 285 010 818	3000
Azera	95910-3L100 Bosch 0 285 001 819	3000
Azera	95910-3L150	3000
Azera	95910-3L450	3000
Azera	95910-3L500 Delphi SA3104100 Bosch 0 285 001 820	3000
Coupe	95910-2C100	3000
Coupe	95910-2C200	3000
Coupe	95910-2C300	3500
Coupe	95910-2C500	3500
Coupe	95910-2C700	3500
Elantra	95910-2D100	3500
Elantra	95910-2D300	3500
Elantra	95910-2D350	3500
Elantra	95910-2D500 Delphi 09384969	3000
Elantra	95910-2D650 Breed	3000
Elantra	95910-2D700 Delphi 12232969	3500
Elantra	95910-2D710 Delphi 12232979	3000
Elantra	95910-2D720 Delphi	3000
Elantra	95910-2H000 Mobis	3000
Elantra	95910-2H100 Mobis	3000

Elantra	95910-2H200 Mobis	3000
Elantra	95910-2H500 Mobis	3000
Elantra	95910-2L020 Mobis 2L959-10020	3000
Elantra	95910-2L030 Mobis 2L959-10030	3000
Elantra	95910-2L050 Mobis 2L959-10050	3000
Elantra	95910-2L060 Mobis 2L959-10060	3000
Elantra	95910-2L130 Mobis 2L959-10130	3000
Entourage	95910-4D100 Mobis	3000
Entourage	95910-4D850 Mobis	3000
Galloper	HR806600	3500
Genesis	95910-2M000 Delphi SA3109800-00 Bosch 0 285 010 3402	3500
Genesis	95910-2M100 Delphi SA3109900-00 Bosch 0 285 010 3581	3581
Genesis	95910-2M200 Delphi SA3110000-00 Bosch 0 285 010 3580	3580
Getz	95910-1C000	2500
Getz	95910-1C010	2500
Getz	95910-1C100 TRW	3000
Getz	95910-1C150 Mobis	3000
Getz	95910-1C200 TRW	3000
Getz	95910-1C250 Mobis	3000
Getz	95910-1C260 Mobis	3000
Getz	95910-1C270 Mobis	3000
Getz	95910-1C600 Mobis	2500
Getz	95910-1C650 Mobis	3000
Getz	95910-1C780 Mobis	3000
Getz	95910-1E150 Mobis	3000
Grandeur	95910-3L150	3000
Grandeur	95910-3L460 Delphi SA3112800 Bosch 0 285 001 3350	3350
H1	95900-4A301	3500
H1	95900-4A500	3500
H1	95910-4H500 Delphi SA3107100-00 Bosch 0 285 001 3924	3924
i10	95910-0X000 Siemens 5WK43793	3000
i10	95910-0X100 Siemens 5WK43794	3000
i10	95910-0X200 Siemens 5WK43795	3000
i20	95910-1J000	3000
i20	95910-1J100	3000
i20	95910-1J200	3000
i20	95910-1J400	3000
i30	95910-2L020 Mobis 2L959-10020	3000
i30	95910-2L030 Mobis 2L959-10030	3000
i30	95910-2L050 Mobis 2L959-10050	3000
i30	95910-2L060 Mobis 2L959-10050	3000
i30	95910-2L120 Mobis	3000
i30	95910-2L130 Mobis 2L959-10130	3000
i30	95910-2R000 Mobis 2R959-10000	3000
i30	95910-2R100 Mobis 2R959-10100	3000
ix35	95910-2S000 Delphi 28170616	3500

ix35	95910-2S000 Delphi 28267123	3500
ix35	95910-2S000 Delphi 28309523	3500
ix35	95910-2S200 Delphi	3500
ix35	95910-2S500 Delphi	3500
ix35	95910-2Y100 Delphi 28267134	3500
ix55	95910-3J000 Autoliv	3500
ix55	95910-3J100 Autoliv	3500
ix55	95910-3J200 Autoliv 606231007B	3500
ix55	95910-3J300 Autoliv	3500
ix55	95910-3J400 Autoliv	3500
ix55	95910-3J500 Autoliv 606231005B	3500
ix55	95910-3J900 Autoliv 606231006B	3500
Matrix	95910-10100	3500
Matrix	95910-10210	3500
Matrix	95910-17050	3500
Matrix	95910-17100 Delphi 12210169	3500
Matrix	95910-17150 Delphi 28035844	3500
Matrix	95910-17600 Delphi 12210199	3500
Matrix	95910-17650 Delphi 21004122	3500
Santa Fe	95910-0W000 Delphi SA3104800 Bosch 0 285 001	<del>3000</del> 3200
Santa Fe	95910-0W100 Delphi SA3114500-00 Bosch 0 285 010	<del>3000</del> 3020
Santa Fe	95910-26100 Siemens 5WK2951	3000
Santa Fe	95910-26200 Siemens 5WK42952	3000
Santa Fe	95910-26500 Siemens 5WK43043	3000
Santa Fe	95910-26600 Siemens 5WK43044	3000
Santa Fe	95910-26700 Siemens 5WK43045	3000
Santa Fe	95910-27350	3500
Santa Fe	95910-29750	3500
Santa Fe	95910-2B170 Delphi SA3108800 Bosch 0 285 010	<del>3000</del> 3070
Santa Fe	95910-2B270	3000
Santa Fe	95910-2B400 Delphi SA3105100 Bosch 0 285 001	<del>3000</del> 3070
Santa Fe	95910-2B470 Delphi SA3109100 Bosch 0 285 010	<del>3000</del> 3060
Santa Fe	95910-2B600 Delphi SA3105500 Bosch 0 285 001	<del>3000</del> 3050
Santa Fe	95910-2B670 Delphi SA3109300 Bosch 0 285 010	<del>3000</del> 3200
Santa Fe	95910-2B770 Bosch 0 285 010 121	3000
Santa Fe	95910-2B900 Bosch	3000
Santa Fe	95910-2B970 Delphi SA3109600 Bosch 0 285 010	<del>3000</del> 3200
Sonata	95910-0A000 Mobis	3000
Sonata	95910-0A010 Mobis	3000
Sonata	95910-3D100 Siemens	3000
Sonata	95910-3D200 Siemens 5WK43067	3000
Sonata	95910-3K000 Mobis	3000
Sonata	95910-3K010 Mobis 3K959-10010	3000
Sonata	95910-3K100 Mobis	3000
Sonata	95910-3K110 Mobis 3K959-10110	3000
Sonata	95910-3K200 Mobis	3000

Sonata	95910-3K210 Mobis 3K959-10210	3000
Sonata	95910-3K300 Mobis	3000
Sonata	95910-3K400 Mobis	3000
Sonata	95910-3K410 Mobis	3000
Sonata	95910-3K500 Mobis	3000
Sonata	95910-3Q000 Mobis 3Q959-10000	3000
Sonata	95910-3Q010 Mobis 3Q959-10010	3000
Sonata	95910-3S000 Mobis 3S959-10000	3000
Sonata	95910-3S100 Mobis 3S959-10100	3000
Sonata	95910-3S110 Mobis 3S959-10110	3000
Starex	95900-4A401	3500
Starex	95900-4A500	3500
Starex	95910-4H500 Delphi SA3107100-00 Bosch 0 285 00 19024	3500
Terracan	95910-H1200 Sungwoo	3000
Terracan	95910-H1300	3500
Terracan	95910-H1400	3500
Terracan	95910-H1500	3500
Terracan	95910-H1600	3500
Tiburon	95910-27350	3500
Tiburon	95910-2C100	3500
Tiburon	95910-2C200	3000
Tiburon	95910-2C300	3500
Tiburon	95910-2C400	3500
Tiburon	95910-2C500	3500
Tiburon	95910-2C700	3500
Tiburon	95910-2E700 Bosch 4070934-4474 Delphi SA310233500	3500
Trajet	95910-3A100	3000
Trajet	95910-3A600	3500
Tucson	95910-2E000 Bosch 407934-4404 Delphi SA310133000	3000
Tucson	95910-2E100 Bosch 407934-4414 Delphi SA310143000	3000
Tucson	95910-2E200 Bosch 407934-4424 Delphi SA310183500	3500
Tucson	95910-2E210 Bosch 407934-7290 Delphi SA311153500	3500
Tucson	95910-2E300 Bosch 407934-4434 Delphi	3000
Tucson	95910-2E310 Bosch 407934-7300 Delphi SA311163500	3500
Tucson	95910-2E400 Bosch 407934-4444 Delphi SA310203000	3000
Tucson	95910-2E410 Bosch 407934-7310 Delphi SA3111700000	3000
Tucson	95910-2E500 Bosch 407934-4454 Delphi SA310213500	3500
Tucson	95910-2E600 Bosch 407934-4464	3500
Tucson	95910-2E610 Bosch 407934-7330 Delphi SA311193500	3500
Tucson	95910-2E700 Bosch 407934-4474 Delphi SA310233000	3000
Tucson		3500
Tucson	95910-2S000 Delphi 28170616	3000
Tucson	95910-2S000 Delphi 28267123	3000
Tucson	95910-2S000 Delphi 28309523	3000
Tucson	95910-2S200 Delphi	3000
Tucson	95910-2S500 Delphi	3000

Veloster	95910-2V200 Delphi 28312634	3000
Veracruz	95910-3J000 Autoliv	3500
Veracruz	95910-3J100 Autoliv	3500
Veracruz	95910-3J200 Autoliv 606231007B	3500
Veracruz	95910-3J300 Autoliv	3500
Veracruz	95910-3J400 Autoliv	3500
Veracruz	95910-3J500 Autoliv 606231005B	3500
Veracruz	95910-3J900 Autoliv 606231006B	3500
Veracruz	95910-1E000 Mobis 2E959-10000	3500
Veracruz	95910-2H000 Mobis 2H959-10000	3500
Veracruz	95910-2H200 Mobis 2H959-10200	3500
XG30	95910-39900 Siemens 5WK43215	3000
XG30	95910-3C200	3500
XG30	95910-3C400	3500