

Стоимость ремонта снятых с автомобиля электронных блоков безопасности (SRS) автомобиля марки Kia: 2500 - 4000 рублей.

Модель	Номер блока	Стоимость ремонта
<del>95910-2J000</del>	Delphi SA3107900-00 Bosch 0 285 010 014	3500
<del>95910-2J450</del>	Delphi SA3108500-00 Bosch 0 285 010 018	3500
<del>95910-2J550</del>	Delphi SA3108600-00 Bosch 0 285 010 019	3500
<del>95910-1D000</del>	Mobis 1D959-10000 Bosch 0 285 001 915	3500
<del>95910-1D100</del>	Mobis 1D959-10100 Bosch 0 285 001 916	3500
Carens	95910-1D200 Mobis 1D959-10200 Bosch 0 285 001 9173000	3000
Carens	95910-1D300 Mobis 1D959-10300 Bosch 0 285 001 9183000	3000
Carens	95910-1D400 Mobis 1D959-10400 Bosch 0 285 001 9193000	3000
Carens	95910-1D500 Mobis 1D959-10500 Bosch 0 285 001 9203000	3000
Carens	95910-1D600 Mobis 1D959-10600 Bosch 0 285 001 9213000	3000
Carnival	0 K54C 67 7F0A Mobis	3500
Carnival	95910-4D160 Mobis 4D959-10160	3000
Carnival	95910-4D220 Mobis 4D959-10220	3000
Carnival	95910-4D330 Mobis 4D959-10330	3000
Carnival	95910-4D930 Mobis 4D959-10930	3000
Ceed	95910-1H000 Mobis 1H959-10000	2500
Ceed	95910-1H100 Mobis	3000
Ceed	95910-1H200 Mobis	3000
Ceed	95910-1H250 Mobis 1H959-10250	3000
Cerato	95910-1M100 Mobis 1M959-10100	3000
Cerato	95910-1M200 Mobis 1M959-10200	3000
Cerato	95910-1M250 Mobis 1M959-10250	3000
Cerato	95910-1M300 Mobis 1M959-10300	3000
Cerato	95910-1M350 Mobis 1M959-10350	3000
Cerato	95910-1M500 Mobis 1M959-10500	3000
Cerato	95910-1M550 Mobis 1M959-10550	3000
Cerato	95910-1M600 Mobis 1M959-10600	3000
Cerato	95910-2F100 Mobis	2500
Cerato	95910-2F200 Mobis	3000
Cerato	95910-2F250 Mobis	3000
Cerato	95910-2F500	3000
Cerato	95910-2F610 Mobis 2F959-10610	2500
Cerato	95910-2F700 Mobis	3000
Cerato	95910-2F710 Mobis	3000
Forte	95910-1M100 Mobis 1M959-10100	3000
Forte	95910-1M200 Mobis 1M959-10200	3000
Forte	95910-1M250 Mobis 1M959-10250	3000
Forte	95910-1M300 Mobis 1M959-10300	3000
Forte	95910-1M350 Mobis 1M959-10350	3000
Forte	95910-1M500 Mobis 1M959-10500	3000

Forte	95910-1M550 Mobis 1M959-10550	3000
Forte	95910-1M600 Mobis 1M959-10600	3000
Grand Carnival	95910-4D850 Mobis	3000
Grand Carnival	95910-4H500 Delphi SA3107100-00 Bosch 0 285 001 924000	3000
Magentis	95910-2G100 Autoliv	3000
Magentis	95910-2G150 Autoliv 20080523	3000
Magentis	95910-2G200 Autoliv	3000
Magentis	95910-2G400	3000
Magentis	95910-2T100 Mobis 2T959-10100	3000
Magentis	95910-3C200	3000
Mohave	95910-2J000 Delphi SA3107900-00 Bosch 0 285 010 0143500	3500
Mohave	95910-2J450 Delphi SA3108500-00 Bosch 0 285 010 0183500	3500
Mohave	95910-2J550 Delphi SA3108600-00 Bosch 0 285 010 0193500	3500
Opirus	95910-3F000 Siemens 5WK43216	3500
Opirus	95910-3F500 Siemens 5WY67043	3500
Opirus	95910-3F850 Siemens 5WY67050	3500
Optima	95910-2G000 Autoliv	3000
Optima	95910-2G400	3000
Optima	95910-2T100 Mobis 2T959-10100	3000
Optima	95910-3C200	3500
Picanto	95910-07000	2500
Picanto	95910-07100 Mobis	2500
Picanto	95910-07120 Mobis	2500
Picanto	95910-07200 Mobis	2500
Picanto	95910-07500 Mobis 07959-10500	2500
Picanto	95910-07600 Mobis 07959-10600	2500
Picanto	95910-07620 Mobis 07959-10620	2500
Picanto	95910-07700 Mobis 07959-10700	2500
Pride	95910-1G000 Mobis	3000
Rio	0K30E 677F0	3500
Rio	0K32B 677F0	3500
Rio	95910-1G000 Mobis	3000
Rio	95910-1G020 Mobis	3000
Rio	95910-1G120 Mobis	3000
Rio	95910-1G150 Mobis	3000
Rio	95910-1G210 Mobis 1G959-10210	3000
Rio	95910-1G250 Mobis	3000
Rio	95910-1G650 Mobis 1G959-10650	3000
Rio	95910-1G900 Mobis	3000
Rondo	95910-1D000 Mobis 1D959-10000 Bosch 0 285 001 9153000	3000
Rondo	95910-1D100 Mobis 1D959-10100 Bosch 0 285 001 9163000	3000
Rondo	95910-1D200 Mobis 1D959-10200 Bosch 0 285 001 9173000	3000
Rondo	95910-1D300 Mobis 1D959-10300 Bosch 0 285 001 9183000	3000
Rondo	95910-1D400 Mobis 1D959-10400 Bosch 0 285 001 9193000	3000
Rondo	95910-1D500 Mobis 1D959-10500 Bosch 0 285 001 9203000	3000
Rondo	95910-1D600 Mobis 1D959-10600 Bosch 0 285 001 9213000	3000

Rondo	95910-2G000 Autoliv	3000
Sedona	95910-4D160 Mobis 4D959-10160	3500
Shuma	0 K2D K 67 7F0	2500
Sorento	95910-3E000 Siemens	3500
Sorento	95910-3E050 Siemens 5WK43061	3500
Sorento	95910-3E060 Siemens 5WY67056	3500
Sorento	95910-3E080 Siemens 5WY67096	3500
Sorento	95910-3E100 Siemens 5WK43062	3500
Sorento	95910-3E200 Siemens 5WK43245	3500
Sorento	95910-3E400 Siemens 5WK43247	3500
Sorento	95910-3E700 Autoliv 604 55 86 00	3500
Soul	95910-2K000 Mobis 2K959-10000 Continental 5K43976	3500
Soul	95910-2K050 Mobis 2K959	3500
Soul	95910-2K110 Mobis 2K959-10110 Continental 5WK4397	3500
Soul	95910-2K150 Mobis 2K959-10150 Continental 5WK4417	3500
Soul	95910-2K200 Mobis 2K959-10200 Continental 5WK4397	3500
Soul	95910-2K210 Mobis 2K959-10210 Continental 5WK4397	3500
Soul	95910-2K250 Mobis 2K959-10250 Continental 5WK4417	3500
Soul	95910-2K310 Mobis 2K959-10310 Continental 5WK4397	3500
Soul	95910-2K350 Mobis 2K959-10350 Continental 5WK4417	3500
Spectra	0 K2DK 67 7F0B Mobis FB959-10100	3000
Spectra	95910-2F400	2500
Spectra	95910-2F450	3000
Spectra	95910-2F600 Mobis	3000
Spectra	95910-2F900	3000
Sportage	0 K082 67 7F0A	3000
Sportage	95910-0Z000 Mobis-Bosch	3500
Sportage	95910-0Z100 Mobis-Bosch	3500
Sportage	95910-0Z200 Mobis 0Z959-10200 Bosch 407934-7421	3500
Sportage	95910-0Z300 Mobis-Bosch	3500
Sportage	95910-0Z400 Mobis 0Z959-10400 Bosch 407934-7580	3500
Sportage	95910-1F000 Bosch 407934-4646	3500
Sportage	95910-1F100 Delphi SA3102700-00 Bosch 407934-4656	3500
Sportage	95910-1F110 Delphi SA3110900-00 Bosch 407934-7360	3500
Sportage	95910-1F200 Delphi SA3102800-00 Bosch 407934-4666	3500
Sportage	95910-1F210 Delphi SA3111000-00 Bosch 407934-7370	3500
Sportage	95910-1F300 Delphi SA3102900-00 Bosch 407934-4674	3500
Sportage	95910-1F310 Delphi SA3111100-00 Bosch 407934-7380	3500
Sportage	95910-1F400 Delphi SA3103000-00 Bosch 407934-4684	3500
Sportage	95910-1F410 Delphi SA3111200-00 Bosch 407934-7390	3500